

BUILDING SAFETY CERIFICATE

No. 2025-26/1539

Date: 23/04/2026

It is certified that the existing building Sunrise NAVI International School at 9th Mile Stone, Bone Mill, Bangalore, Hesaraghatta Main Road, Bengaluru – 560073 is having is having block(s)/floor(s) as per details below:

Detail of the block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of floor(s) in the block	Ground + 3	Ground + 4	----	----	----	----

The building owned by/occupied by Sunrise NAVI International School have complied with the building safety requirements in accordance with National Building code rules, and verified by the officers concerned of Assistant Executive Engineer on 23/04/2026 in the presence of Principal and that the building/premises is fit for occupancy for running school with effect from 23/04/2026 for a period of three years in accordance with rule and subject to compliance of the specific conditions as appended.

1. No additional floors of constructions are permitted.
2. It is essential that the above said building should undergo necessary annual and special maintenance wherever required

Issued on 23/04/2026 at Bangalore by



Assistant Executive Engineer
No. 4, Buildings, Sub-Division
Bangalore - 560 001.

Name : Akhilan. L.D
Designation : Assistant Executive Engineer
Name & Address of Department/ Office: Office of the Assistant Executive Engineer
No.4 Buildings Subdivision,
Public Works Department, KR Circle,
Bangalore-560001 Bangalore



Principal
Principal

Sunrise NAVI International School
9th Mile Stone, Bonemill,
Hesaraghatta Main Road,
Bagalgunte, Bengaluru-560 073



Secretary

Sunrise NAVI International School
9th Mile Stone, Bonemill,
Hesaraghatta Main Road,
Bengaluru, Bengaluru-560 073